



West gate, March 2001



Atmospheric area has rust stains bleeding from joints.



Skin side of gate.



Zebra mussels on lower portion of gate.



Corrosion due to poor application on edges.



Most corrosion is application related.